			REVISEO 10-14-86
FHEA NO		SINITLE CCTV CRITICAL TIEMS LIST	UNIT Video Switching Unit (VSU) 0H6 NO. 2294823-502, 504 SHEET 1 OF 7
FAILURE MODE AND FAILURE EFFECT		RATIONALE FOR ACCEPTANCE	
CAUSE Power on reset (POR) remains in high state. Cause: (1) Microprocessor, 1/0, A1, 2592389-501 or 2294889-502	Nicrocomputer and associated logic remains in reset state. Signal routing not possible. Worst Case: Cannot select camera signal for display on monitor or for downlink.	RATIONALE FOR ACCEPTANT DESIGN FEATURES The VSU is a microprocessor—based video switching unimicroprocessor, CMOS RAM, and ITL PROM. Computer 1/0 and switch control circuitry are implemented in CMOS power dissipation. The design incorporates DMOS FET an RCA spec control drawing (SCD) as the basic video split—screen capability incorporates glass delay line Microsonics (originally Corning) to an RCA SCD. The monolithic NESS39 wideband op amps in a fashiun simil employed in the RCU. Parts were required to be JAN reliability level parts selection falls into three categories: (1) JAM or better parts from the Military QPL. (2) Parts demonstrated to NASA to be equivalent (e.g., CD4000/3M series parts), or (3) Parts procured to an RCA spec control drawin screening to effect JAM equivalency. BARE BOARD CONSTRUCTION (A1) The boards are of "welded wire" construction. At the distinguish it from a normal PC board except that hol generally are not connected to PC traces. Only those ground patentials to the ICs are on PCs. An annular board where each power and ground pin is located. The the trace like any other component lead. Aside from 8 construction techniques used in PC board layout app BOARD ASSEMBLY (A1) The drilled and etched boards are populated with seve weldable pins. Power and ground pins, as well as con place. Discreet components (resistors, diades, capac bifurcated terminals, where they are soldered. Flatp lead—by-lead, to the tops of the weld pins. After well trimmed away. Circuit connections are made using A30 wire is welded to the pin surfaces on the board backs using a machine which is tape driven, thus eliminatin due to uperator error. All wiring 8 circuit performa box—level installation. After successful testing, co	Lusing an RCA 1802 , decoding logic, digital audio CD4000 series logic to minimize devices (SD211s) purchased to switch element. Video modules procured from video amplifier design uses ar to the sync amp design of their equivalent. Part to JAH level via test data g which calls out tests and bare board level this does not es which will take weld pins pins which bring power and ring surrounds the hule in the ase pins are then soldered to this feature, all design ly. ral hundred solderable or nector pins, are soldered in itors; are attached to ack ICs are welded, ding, extra lead material is AWG nickel weld wire. The ide. All wire welds are done g the possibility of miswiring nce is Lested prior to

FMEA NO. 1.2.22		SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT <u>Video Switching Unit (VSU</u> DMG NO. <u>2294823-502, 504</u> SHEET <u>2</u> OF		
falture mode amb (AUSF Power on reset (POR) remains in high state. Cause: (1) Microprocessor, I/O, A1, 2592389-501 or 2294889-502	FATTURE EFFECT ON FND IJEM Nicrocomputer and associated logic remains in reset state. Signal routing not possible. Morst Case: Cannot select camera signal for display on monitor or for downlink.	DESIGN FEATURES The board is inserted in the box on card-edge guide PC boards. BOARD PLACEMENT The Al board is secured in the electronics assembly guide-plated beryllium copper card guides. Connecti	copper card guides. Connections are made to the mother board ctors. Disengagement during launch is prevented by a cover		

REVISED 10-14-86

FMLA NO. 1.2.22	· -	SHUTTLE CCTV CRITICAL CIERS LIST	Video Smitching Unit (VS) NO. 2294623-502, 504 T3 OF7
EATLINE MIDE AND L. FATLINE FEECT		318-1	, <u> </u>
FAILURE MUDE AND (AUSE Cover on reset (POR) remains In high state. Janke: Author		PARTICIPATE FOR ACCEPTANCE QUALIFICATION TEST For Qualification Test flow, see Table 2 Incated at the front ACCEPTANCE TEST The CCTV systems' VSU is subjected to the following testing: • Vibration: 20-BDHz: 3 dB/Oct-Fire from 0.01 G²/Hz 80-350 Hz: 0.04 G²/Hz 350-750 Hz: 3 dB/Oct-Fall to 0.018 G²/Hz 750-100D: 0.018 G²/Hz 1000-2000: 3 dB/Oct-Fall to 0.009 G²/Hz	to 0.04 G ² /Hz r r r this book. t must verify the 1) panel switch, the Camera/PTU command oduce video, the VSU's ideo. A similar test d the camera under eo on munitor is s that the camera camera is producing and visually (either on. as source.
338		This proves that the CCTV equipment is operational.	

FMEA NO		SHUTTLE CCTV CRITICAL ITEMS LIST		ONIT VIDEO SWITCHING UNIT 195 DWG NO. 2294823-502. 504 SHEET 4 OF 7			
CRITICALITY 2/2			SHEET	. <u>-4</u>	ßF	:	
FAILUNE MODE AND FAILURE EFFECT CAUSE ON END LIEM		RATIUNALE FOR ACCEPTANCE					
Power on reset (POR) remains in high state. [ause: {1} Microprocessor, 1/0, At. 2592389-501 or 2294889-502	Microcomputer and associated logic remains in reset state. Signal routing not possible. Worst Case: Cannot select camera signal for display on monitor or for downlink.	Procurement Control - The VSU Parts and hardware items vendors and suppliers, which meet the requirements set Quality Plan Work Statement [MS-2593176]. Resident DC procurement documents to establish the need for GSI on Incoming Inspection and Starage - Incoming Quality ins received materials and parts. Results are recorded by drawing and control numbers for future reference and subjected to incoming acceptance tests as called for itest Instructions. Incoming flight parts are further RCA 1846684 - Preconditioning and Acceptance Requirements are exception the CPA and PTMD testing is not performed inspected per PAI 316 - Incoming Inspection Instructions Processing Incoming or Purchased Parts Designated for are delivered to Haterial Controlled Stores and retain until fabrication is required. Non-conforming material Board (HRB) disposition. (PAI-307, PAI EQC-531). Board Assembly & Iest - Prior to the start of VSU board verified to be correct by stock room personnet, as the a kit. The items are verified again by the operator checking against the as-built-parts-list (ABPL). DCAS are designated for all printed circuit, wire wrap and harness connectors for soldering wiring, crimping, solworkmanship prior to coating of the component side of Specific VSU board assembly and test instructions are applicable documents are called out in the fabrication (FPR-2294823) and parts list P. 2294823. These include (FPR-2294823) and parts list P. 2294823. These includes a part of the component side of Specification - Crimping 2280400, Specification Name P. Specification - Crimping 2280400, Specification - Board Specification - Urethane coating 228047, Specification - Specification - Urethane coating 228047, Specification - Specification - Urethane coating 228047, Specification - Specification - Workmanship 8030035, Specification - Specification - Specification - Specification -	forth in AS personn a selected spections a feat and raceabilities and PAI 315 processed ents for Becking AM PAI 315 are held under saits are held assembly welded wire conflored and PAI are appliced and provided in Procedured and PAI are Appliced and - locking Am - locking Amarking 2 Marking 2 Marking 2	the CCIVel review of review parts (Preview parts (Preview parts (Preview Preview Previ	contra w alt all all AI 517) on all in file EEE par ng Lnsp dence w Parts. ms are items, ocedure ted ite terial ems are ated to it by ion Pai ality g of ha g notes ord List 22 228088 80878, and 2026	by ts are ection ith with PA[for ms ions Review torm ints arnesses. and 295900,	

			8FV[SEU 10-14-8
FMEA NO. 1,2,22 CRITICALITY 2/2		SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT <u>Video Switching Unit (VSU</u> OWG NO. <u>2294823-502</u> 504 SMEET <u>5</u> OF <u>7</u>
FACTURE MODE AND FACTURE EFFECT CAUSE ON END ITEM		RATIONALE FOR ACCEP	TANCE
Power on reset (POR) remains in high state. Cause: (1) Microprocessor, I/D. A), 2592389-501 or 2294889-502	Microcomputer and associated logic remains in reset state. Signal routing well possible. Worst Case: Cannot select camera signal for display on monitor or for downlink.	QA/INSPECTION (Continued) VSU Assembly and Test An open box test is performed per TP-ET-22944832, IP-AT-2294823, including vibration and thermal vac witnessed, traceability numbers are recorded and c to use. RCA quality and DCAS inspections are perf specified FPR operations in accordance with PAI-20 OCAS personnel witness VSU button-up and critical monitor acceptance tests and review test data/resu after all repair, rework and retest. Preparation for Shipment - The VSU is packaged acceptance for packaging and handling guidelines. A assembly drawing, parts list, A8PL, test data, etc ducumentation folder assigned specifically to each retained for reference. An EIDP is prepared for e requirements of WS-2593176. RCA QC and DCAS perso packing and marking, and review the EIDP for compl	count. Torques are specified and calibrated lools are check prior ormed at the completion of 4, PAI-205, PAI-206, and PAI-217. torquing. RCA and DCAS personnel alts. These personnel also inspect cording to 2280746. Process all related documentation including to 3 gathered and held in a cassembly. This folder is each VSU in accordance with the wonel witness crating, packaging,
·			

FNEA NO		SHUTTLE CCTV CRITICAL ITEMS LEST	UNIT <u>Video Switching Unit (VSU)</u> ONG NO. 22 <u>94823-502. 504</u> SHEET <u>6</u> OF 7
FAILURE HODE AND CAUSE Power on reset (POR) remains in high state. Lause: (1) Microprocessor, 1/0, A1, 2592389-501 or 2294889-502	FATEURE EFFECT ON END 118H Microcompuler and associated logic remains in reset state. Signal routing not possible. Worst Case: Cannot select camera signal for display on monitor or for downlink.	EATLURE HISTORY NONE.	
	1	1	

			REVISEO 10-14-86	
FMEA NO		SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT <u>Video Switching Unit (VSU</u> OWG NO. <u>2294823-502, 504</u> SHEELOF	
FAILURE MODE AND CAUSE Power on reset (POR) remains in high state. Cause: (1) Microprocessor, 1/0, A1, 2592389-501 or 2294889-502	FAILURE EFFECT ON END TIEM Microcomputer and associated logic remains in reset state. Signal rowling not possible. Worst Case: Cannot calect camera signal for display on monitor or for downlink.	RATIONALE FOR ACCEPTANCE OPERATIONAL EFFECTS Loss of video. Possible loss of major mission objective or other required cameras. CREW ACTIONS If possible, continue RMS operations using alternative CREW TRAINING Crew should be trained to use possible alternatives to MISSION CONSTRAINI Where possible, procedures should be designed so they continue possible, procedures should be designed so they continue possible, procedures should be designed so they continue possible.	jectives due to loss of RMS cameras ative visual cues.	
		сстv. '		
	*			